


**TABELLA GIUNTI DI SMONTAGGIO**  
**DISMANTLING JOINTS TABLE - TABLE DES JOINTS DE RETRAITS**

DN	Due flange Double flanged - Deux brides		Tre flange Triple flanged - Trois brides		
	L	C	L max.	L min.	C
40	95	5	200	170	25
50	95	5	200	170	25
65	5	5	200	170	25
80	95	5	200	170	25
100	95	5	200	170	25
125	95	5	200	170	25
150	105	5	200	170	25
200	115	5	220	190	25
250	115	5	220	190	25
300	115	5	220	190	25
350	125	5	220	190	25
400	135	5	250	190	25
450	135	5	250	220	25
500	135	5	280	140	25
600	150	5	280	240	30
700	150	5	320	270	40
800	180	5	320	270	50
900	180	5	350	290	60
1000	210	5	350	290	60
1200	210	5	400	320	80
1400	230	5	450	360	90
1600	250	5	500	400	100
1800	250	5	550	430	120
2000	250	5	600	460	140



C=corsa – stroke – course